Part –I Performa for the Safety School Building (To be filled by the Head of School/Institute)

1	Nam	e of the School	TAGORE INTERNATIONAL SCHOOL	
2	Loca	tion	KOHARA ROAD SAHNEWAL	
3	Plot	Area	3.5 ACRES	
4	Plinth Area		25444 SQ FEET	
5	Num	ber of Storey	GROUND + TWO	
6	Year of construction of building		2001	
7	Supervision of the qualified Engineer			
	The	following details may be given:		
	a)	Name of the Engineer	MR.ASHISH SODHI	
	b)	Address	BRS NAGAR LUDHIAN	A
	c)	Set of structure Drawing used in th	е	
		construction if available	THREE NO'S	
	d)	Name of Architect	MR.ASHISH SODHI	
8	Whether the building has been constructed for the purpose of :			
	a)	School	44.	(Yes/No) YES
	b)	Residential purpose and covered for	or use as a school	(Yes/No) YES
9	Material used for roof			
	a)	RCC Slab		(Yes/No) YES
	b)	RS Joists and Battens		(Yes/No)
	c)	Wooden joist and Battens		(Yes/No)
10	Material used for walls			
	a)	Mud Motor		(Yes/No)
	b)	Cement Motor		(Yes/No) YES
	c)	Plaster i) Lime Motor		(Yes/No)
		ii) Cement Motor		(Yes/No) YES
11.	Flooring a) Conglomerate b) Terazzo c) Brick Paving For Tagore International School For Tagore International Cashle			
	a)	Conglomerate	national School	(Yes/No)
	b)	Terazzo	s Internal	(Yes/No) YES
	c)	Brick Paving For	Carle Marie	(Yes/No)
12.	Deta	iled Drawing Indicating dimensions of	the rooms	
	along with size and location of doors and windows			ATTACHED

Part-II (To be filled by S.D.E of P.W.D B&R Department)

I have visited the above mentioned school on 11 d 2003 inspected it from all angles of safety and I found it fit fort normal use as school building.

In case any addition/ alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of work from the undersigned.

In case the building is affected by flood or if there is settlement of walls/ foundations or caves of root etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.

This building can be safely occupied for normal use up to 3103 2024

(indicate

year up to which it can be used)

Recept No - 5613369 Date = 17/04/23

ENSM NO 85 Dele 25/05/23

For Tagore International School